# LIEBHERR

CONSTRUCTION EQUIPMENT

## LIEBHERR LH30 1200-72683 - Splitter Box

**Sample No:** LH06063163

Calcium

Zinc

Barium

Boron

Magnesium

Phosphorus

ppm

ppm

ppm

ppm

ppm

ppm

Oil Type: GEAR OIL SAE 80W90



167

**19** 

 $\bigcirc$  72

0 472

 $\bigcirc$  0

02





### SPARTAN RECYCLING 3071 HOWARD ST SPARTANBURG, SC US 29303

Contact: SERVICE MANAGER

T: F:

37

 $\bigcirc$  7

29

374

 $\bigcirc$  0

13

#### Diagnosis

No corrective action is recommended at this time. The oil change at the time of sampling has been noted. Resample at the next service interval to monitor. Gear wear is indicated. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:SPASPALHUnique No:10834545Signed:Sean FeltonReport Date:19 Jan 2024

**43** 

**9** 

**25** 

395


**3** 

ISTRUCTION EQUIPMENT





#### **GRAPHS**



Report Id: SPASPALH [WUSCAR] 06063163 (Generated: 01/19/2024 13:19:07) Rev: 1