LIEBHERR

CONSTRUCTION EQUIPMENT

LIEBHERR LH30M 117414-1253 - Rear Left Wheel Hub

Sample No: LH0272897

Oil Type: GEAR OIL SAE 80W90

SAMPLE INFORMATION					
Sample Number	LH0272897	LH0235755	LH0217608		
Sample Date	10 Jan 2024	26 Sep 2023	14 Jul 2022		
Machine Hours	8285	7700	0		
Oil Hours	0	0	0		
Oil Changed	Changed	Changed	N/A		
Sample Status	NORMAL	NORMAL	ABNORMAL		

OIL CO	NDITION				
Visc @ 40°C	cSt	121	97.2	95.0	

CONTAMINATION						
Water	%	NEG	NEG	NEG		
Silicon	ppm	2	5	O 11		
Sodium	ppm	0	4	4		
Potassium	ppm	1	O 2	3		

(O)					
WEA	R META	LS			
Iron	ppm	17	45	547	
Copper	ppm	0 1	4	4	
Lead	ppm	0	0	O 0	
Tin	ppm	0	0	<1	
Aluminum	ppm	2	<1	1	
Chromium	ppm	() <1	 <1	O 2	
Molybdenum	ppm	1	4	<1	
Nickel	ppm	0	O 0	<1	
Titanium	ppm	0	0	0	
Silver	ppm	0	0	0	
Manganese	ppm	0	<1 <1	4	
Vanadium	ppm	0	<1	<1	

variaululli	ppiii	U	< 1	< 1	
ADDI	TIVES				
Calcium	ppm	67	O 217	25	
Magnesium	ppm	6	18	5	
Zinc	ppm	0	O 99	17	
Phosphorus	ppm	364	426	260	
Barium	ppm	3	O 0	0	
Boron	ppm	1	14	3	



SPARTAN RECYCLING 3071 HOWARD ST SPARTANBURG, SC US 29303

Contact: SERVICE MANAGER

Т	:
F	
	•

Diagnosis

Resample at the next service interval to monitor. Please specify the brand, type, and viscosity of the oil on your next sample. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:SPASPALHUnique No:10834554Signed:Wes DavisReport Date:18 Jan 2024

CONSTRUCTION EQUIPMENT





GRAPHS

