# CONSTRUCTION EQUIPMENT



### LIEBHERR LTM1070-4.2060759-3-Right Wheel Hub

Sample No: LH0259064

Oil Type: EP 90

Barium

Boron

ppm

ppm

_				
J	<b>PLE INFO</b>	DRMATION		
Sample Number		LH0259064	 	
Sample Date		23 Jan 2024	 	
Machine Hours		0	 	
Oil Hours		0	 	
Oil Changed		Changed	 	
Sample Status		NORMAL	 	
OILC	ONDITIO	ON		
Visc @ 40°C	cSt	<b>148</b>	 	
CONT	TAMINA	TION		
Water	%	NEG	 	
Silicon	ppm	<b>15</b>	 	
Sodium	ppm	<b>6</b>	 	
Potassium	ppm	<b>1</b>	 	
WEA	RMETA	<b>LS</b> ○ 374	 	
Copper	ppm	O 21	 	
Lead	ppm	0 <1	 	
Tin	ppm	0	 	
	ppm	-		
Aluminum	ppm	01	 	
Chromium	ppm	<b>3</b>	 	
Molybdenum	ppm	<1	 	
Nickel	ppm	O <1	 	
Titanium	ppm	<1 0	 	
Silver	ppm	•	 	
Manganese	ppm	4	 	
Vanadium  ADDI	ppm ITIVES	0	 	
Calcium	ppm	51	 	
Magnesium	ppm	0	 	
Zinc	ppm	81	 	
Phosphorus	ppm	730	 	

LIEBHERR USA CO - MOBILE AND CRAWLER CRANES 4100 CHESTNUT AVENUE NEWPORT NEWS, VA US 23607

Contact: TERENCE VANDERLENDE TERENCE.VANDERLENDE@LIEBHERR.COM

T: F:

#### Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:LIENEWUnique No:10847907Signed:Wes DavisReport Date:26 Jan 2024

# CONSTRUCTION EQUIPMENT





### **GRAPHS**

