

LIEBHERR

CONSTRUCTION EQUIPMENT



LIEBHERR LH110 1227-155752 - Rear Left Wheel Hub

Sample No: LH0280567

Oil Type: GL-5



KINDER MORGAN
4301 IVERSON
TRINITY, AL
US 35601
Contact: CHIP OAKES

T: (256)350-0006
F: (256)355-5250

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.



SAMPLE INFORMATION

Sample Number	LH0280567	---	---	---
Sample Date	11 Jan 2024	---	---	---
Machine Hours	507	---	---	---
Oil Hours	0	---	---	---
Oil Changed	Not Chngd	---	---	---
Sample Status	NORMAL	---	---	---



OIL CONDITION

Visc @ 40°C	cSt	● 173	---	---	---
-------------	-----	-------	-----	-----	-----



CONTAMINATION

Water	%	NEG	---	---	---
Silicon	ppm	● 8	---	---	---
Sodium	ppm	● 5	---	---	---
Potassium	ppm	● 2	---	---	---



WEAR METALS

Iron	ppm	● 20	---	---	---
Copper	ppm	● 0	---	---	---
Lead	ppm	● 0	---	---	---
Tin	ppm	● <1	---	---	---
Aluminum	ppm	● <1	---	---	---
Chromium	ppm	● 0	---	---	---
Molybdenum	ppm	0	---	---	---
Nickel	ppm	● <1	---	---	---
Titanium	ppm	● 0	---	---	---
Silver	ppm	0	---	---	---
Manganese	ppm	<1	---	---	---
Vanadium	ppm	0	---	---	---



ADDITIVES

Calcium	ppm	136	---	---	---
Magnesium	ppm	2	---	---	---
Zinc	ppm	18	---	---	---
Phosphorus	ppm	1345	---	---	---
Barium	ppm	<1	---	---	---
Boron	ppm	5	---	---	---

Depot: KINTRI
Unique No: 10848683
Signed: Sean Felton
Report Date: 30 Jan 2024



GRAPHS

