

LIEBHERR LH110 1227-155752 - Splitter Box

0 181

Sample No: LH0280563

Oil Type: GL-5

SAMPLE INFORMATION

Sample Number	LH0280563	 	
Sample Date	11 Jan 2024	 	
Machine Hours	507	 	
Oil Hours	0	 	
Oil Changed	Not Changd	 	
Sample Status	NORMAL	 	

OIL CONDITION

Visc @ 40°C

......

cSt

11						
Water	%	NEG				
Silicon	ppm	0 2				
Sodium	ppm	05				
Potassium	ppm	0 2				

WEA WEA	R META	LS		
Iron	ppm	0 10	 	
Copper	ppm	0	 	
Lead	ppm	0	 	
Tin	ppm	○ <1	 	
Aluminum	ppm	○ <1	 	
Chromium	ppm	0	 	
Molybdenum	ppm	0	 	
Nickel	ppm	○ <1	 	
Titanium	ppm	0	 	
Silver	ppm	0	 	
Manganese	ppm	<1	 	
Vanadium	ppm	0	 	

	TIVES			
Calcium	ppm	47	 	
Magnesium	ppm	3	 	
Zinc	ppm	22	 	
Phosphorus	ppm	1902	 	
Barium	ppm	<1	 	
Boron	ppm	<1	 	





KINDER MORGAN 4301 IVERSON

TRINITY, AL US 35601 Contact: CHIP OAKES

T: (256)350-0006 F: (256)355-5250

Diagnosis

Resample at the next service interval to monitor.All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot: Unique No: Signed: **Report Date:**


KINTRI 10848684 Sean Felton 30 Jan 2024





GRAPHS

 \odot



Report Id: KINTRI [WUSCAR] 06072007 (Generated: 01/30/2024 22:30:31) Rev: 1