## LIEBHERR

**CONSTRUCTION EQUIPMENT** 

### LIEBHERR LH110 155976-1227 - Splitter Box

Sample No: LH0280563
Oil Type: SAE 30W

<b>5</b>							
SAMPLEINFORMATION							
Sample Number		LH0280563					
Sample Date		30 Jan 2024					
Machine Hours		534					
Oil Hours		0					
Oil Changed		Not Changd					
Sample Status		NORMAL					
A							

	OIL CC	<b>NDITION</b>						
Visc @	40°C	cSt	<b>183</b>					
CONTAMINATION								
Water		%	NEG					

CONTAMINATION							
Water	%	NEG					
Silicon	ppm	<b>0</b>					
Sodium	ppm	<b>0</b>					
Potassium	ppm	<b>0</b> 1					

WE!	AR META	16		
AA EA	AR MEIA			
Iron	ppm	<b>11</b>	 	
Copper	ppm	<b>1</b>	 	
Lead	ppm	<b>0</b>	 	
Tin	ppm	<b>0</b>	 	
Aluminum	ppm	<b>2</b>	 	
Chromium	ppm	<b>○</b> <1	 	
Molybdenum	ppm	<b>0</b>	 	
Nickel	ppm	<b>0</b>	 	
Titanium	ppm	<b>0</b>	 	
Silver	ppm	0	 	
Manganese	ppm	<b>0</b>	 	
Vanadium	ppm	0	 	

ADDITIVES						
Calcium	ppm	<b>47</b>				
Magnesium	ppm	<b>1</b>				
Zinc	ppm	<b>6</b>				
Phosphorus	ppm	<b>1897</b>				
Barium	ppm	<b>5</b>				
Boron	ppm	<b>()</b> <1				



#### KINDER MORGAN 4301 IVERSON TRINITY, AL US 35601

Contact: CHIP OAKES

T: (256)350-0006 F: (256)355-5250

#### Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot: KINTRI
Unique No: 10863769
Signed: Jonathan Hester
Report Date: 08 Feb 2024

# LIEBHERR







#### **GRAPHS**

