CONSTRUCTION EQUIPMENT

LIEBHERR LH30M 1253-145780 - Rear Differential

Sample No: LH0276604 Oil Type: {unknown}

5						
SAMPLEINFORMATION						
Sample Number		LH0276604				
Sample Date		07 Feb 2024				
Machine Hours		1023				
Oil Hours		0				
Oil Changed		Not Changd				
Sample Status		NORMAL				
A						

The state of the s
70 70
R

TRAM CONSTRUCTION

9279 E KY 8 GARRISON, KY US 41141

Contact: Service Manager

T: F:

	OILCO	NDITION		
Visc @	40°C	cSt	92.7	

CONTAMINATION							
Water	%	NEG					
Silicon	ppm	4					
Sodium	ppm	8					
Potassium	ppm	<1					

WEAI	RMETALS			
Iron	ppm	5	 	
Copper	ppm	2	 	
Lead	ppm	0 <1	 	
Tin	ppm	2	 	
Aluminum	ppm	0	 	
Chromium	ppm	0	 	
Molybdenum	ppm	0	 	
Nickel	ppm	0	 	
Titanium	ppm	0	 	
Silver	ppm	0	 	
Manganese	ppm	1	 	
Vanadium	ppm	0	 	
Manganese	ppm	1	 	

	I
ĭ	t
_	•

ADDITIVES

Calcium	ppm	1910	 	
Magnesium	ppm	<1	 	
Zinc	ppm	779	 	
Phosphorus	ppm	805	 	
Barium	ppm	0	 	
Boron	ppm	74	 	

Diagnosis

Resample at the next service interval to monitor. Please specify the brand, type, and viscosity of the oil on your next sample.All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot: TRAGARLH **Unique No:** 10874187 Signed: Wes Davis **Report Date:** 13 Feb 2024

LIEBHERR

CONSTRUCTION EQUIPMENT





GRAPHS

