LIEBHERR

CONSTRUCTION EQUIPMENT

LIEBHERR LH30M 1253-145780 - Front Differential

Sample No: LH0276603
Oil Type: {unknown}

OIL CONDITION

_						
SAMPLEINFORMATION						
Sample Number		LH0276603				
Sample Date		07 Feb 2024				
Machine Hours		1023				
Oil Hours		0				
Oil Changed		Not Changd				
Sample Status		NORMAL				
A						

TRAM CONSTRUCTION
9279 E KY 8
GARRISON, KY
119 41141

Contact: Service Manager

Diagnosis

Т	
F	
·	

Visc @ 40°C	cSt	○ 65.6				
CONTAMINATION						
Water	%	NEG				
Silicon	ppm	10				
Sodium	ppm	16				
Potassium	ppm	0				
₩EAR METALS						

Resample at the next service interval to monitor. Please specify the brand, type, and viscosity of the oil on your next sample.All component wear rates are normal. There is no
indication of any contamination in the
oil. The condition of the oil is acceptable for the time in service.

WEA	AK ME I A	LS		
Iron	ppm	4	 	
Copper	ppm	○ <1	 	
Lead	ppm	0	 	
Tin	ppm	2	 	
Aluminum	ppm	0	 	
Chromium	ppm	0	 	
Molybdenum	ppm	0	 	
Nickel	ppm	0	 	
Titanium	ppm	0	 	
Silver	ppm	0	 	
Manganese	ppm	3	 	
Vanadium	ppm	0	 	
-				

Variadiani	PPIII	•				
ADDITIVES						
	IIVES					
Calcium	ppm	3428				
Magnesium	ppm	6				
Zinc	ppm	1387				
Phosphorus	ppm	1079				
Barium	ppm	0				
Boron	ppm	136				

Depot:TRAGARLHUnique No:10874188Signed:Don BaldridgeReport Date:14 Feb 2024

LIEBHERR

CONSTRUCTION EQUIPMENT





GRAPHS

