LIEBHERR

CONSTRUCTION EQUIPMENT

LIEBHERR LH30M 1253-145780 - Front Left Wheel Hub

Sample No: LH0276610
Oil Type: {unknown}

Visc

5						
SAMPLEINFORMATION						
Sample Number		LH0276610				
Sample Date		07 Feb 2024				
Machine Hours		1023				
Oil Hours		0				
Oil Changed		Not Changd				
Sample Status		NORMAL				
A						



TRAM CONSTRUCTION 9279 E KY 8

9279 E KY 8 GARRISON, KY US 41141

Contact: Service Manager

T: F:

4	OIL CC	NDITION			
@	40°C	cSt	65.1	 	

CON	CONTAMINATION							
Water	%	NEG						
Silicon	ppm	7						
Sodium	ppm	18						
Potassium	ppm	0						

	1-1-	O -		
WEA	R METAL	S		
Iron	ppm	35	 	
Copper	ppm	9	 	
Lead	ppm	0 0	 	
Tin	ppm	2	 	
Aluminum	ppm	0	 	
Chromium	ppm	○ <1	 	
Molybdenum	ppm	0	 	
Nickel	ppm	0	 	
Titanium	ppm	<1	 	
Silver	ppm	0	 	
Manganese	ppm	<1	 	
Vanadium	ppm	0	 	

Manganese	ppm	<1					
Vanadium	ppm	0					
ADDITIVES							
Calcium	ppm	3435					
Magnesium	ppm	4					
Zinc	ppm	1378					
Phosphorus	ppm	1074					
Barium	ppm	0					
Boron	ppm	136					

Diagnosis

Resample at the next service interval to monitor. Please specify the brand, type, and viscosity of the oil on your next sample. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:TRAGARLHUnique No:10874189Signed:Don BaldridgeReport Date:14 Feb 2024

LIEBHERR







GRAPHS

