LIEBHERR

CONSTRUCTION EQUIPMENT

LIEBHERR L586 035543-461 - Rear Right Wheel Hub

Sample No: LH0268826

Oil Type: CHEVRON DELO GEAR ESI OIL 80W90

5					
U SAM	PLE INF	ORMATION			
Sample Number		LH0268826	LHMC97135		
Sample Date		30 Jan 2024	24 Sep 2015		
Machine Hours		17019	495		
Oil Hours		1000	0		
Oil Changed		Changed	N/A		
Sample Status		NORMAL	ABNORMAL		
OILC	ONDITI	ON			
Visc @ 40°C	cSt	134	O 194.3		
CONTAMINATION					

CONTAMINATION						
Water	%	NEG	NEG			
Silicon	ppm	2	O 12			
Sodium	ppm	1	○ 3			
Potassium	ppm	○ <1	0			
WEAR	RMETALS					

WEA	R METAL	.S		
Iron	ppm	44	O 66	
Copper	ppm	10	S 58	
Lead	ppm	○ <1	O 0	
Tin	ppm	○ <1	0	
Aluminum	ppm	<1	O <1	
Chromium	ppm	○ <1	O <1	
Molybdenum	ppm	0	O 0	
Nickel	ppm	○ <1	O <1	
Titanium	ppm	0	0	
Silver	ppm	0	0	
Manganese	ppm	3	45	
Vanadium	ppm	0	0	

Vanadium	ppm	0	0			
ADDITIVES						
Calcium		O 26	O 17			
Magnesium	ppm	0 5	0 0			
Zinc	ppm	11	○ 68			
Phosphorus	ppm	1561	1789			
Barium	ppm	() <1	O 0			
Boron	ppm	225	() <1			



MIDDLE RIVER MARINE

1771 SOUTH TORRENCE AVE CHICAGO, IL

US 60617

Contact: Scott Molitor

scottmolitor@gomiddleriver.com

T: F:

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:MIDCHIILUnique No:10884147Signed:Sean FeltonReport Date:19 Feb 2024

CONSTRUCTION EQUIPMENT





GRAPHS

