## LIEBHERR

**CONSTRUCTION EQUIPMENT** 

### LIEBHERR LH40M 137231 - Front Left Wheel Hub

Sample No: LH0268827

Oil Type: LIEBHERR GEAR BASIC 90 LS

<b>a</b>							
SAMPLEINFORMATION							
Sample Number		LH0268827					
Sample Date		23 Jan 2024					
Machine Hours		3350					
Oil Hours		1000					
Oil Changed		Changed					
Sample Status		NORMAL					
<b>A</b>							

OIL COI	<b>NDITION</b>			
Visc @ 40°C	cSt	<b>136</b>	 	

CON	ITAMIN	ATION		
Water	%	NEG	 	
Silicon	ppm	<b>0</b> 1	 	
Sodium	ppm	<b>1</b>	 	
Potassium	ppm	<b>2</b>	 	

₩EA	R META	LS		
Iron	ppm	<b>5</b> 4	 	
Copper	ppm	<b>16</b>	 	
Lead	ppm	<b>○</b> <1	 	
Tin	ppm	<b>○</b> <1	 	
Aluminum	ppm	<b>()</b> <1	 	
Chromium	ppm	<b>0</b>	 	
Molybdenum	ppm	<b>0</b>	 	
Nickel	ppm	<b>○</b> <1	 	
Titanium	ppm	<b>0</b>	 	
Silver	ppm	0	 	
Manganese	ppm	<b>1</b>	 	
Vanadium	ppm	0	 	

Vanadium	ppm	0	 	
ADDI				
ADDI'	TIVES			
Calcium	ppm	<b>15</b>	 	
Magnesium	ppm	<b>4</b>	 	
Zinc	ppm	<b>15</b>	 	
Phosphorus	ppm	<b>1409</b>	 	
Barium	ppm	<b>2</b>	 	
Boron	ppm	<b>197</b>	 	



UNITED SCRAP 1545 S CICERO AVE BURR RIDGE, IL US 60527

Contact: Service Manager

T: F:

#### Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the component. The condition of the oil is acceptable for the time in service.

Depot:UNIBURILUnique No:10884148Signed:Don BaldridgeReport Date:18 Feb 2024

# CONSTRUCTION EQUIPMENT





#### **GRAPHS**

