

LIEBHERR LH40M 118823-1215 - Front Left Wheel Hub

Sample No: LH0243909

Oil Type: LIEBHERR GEAR BASIC 90 LS

SAMPLE INFORMATION

Sample Number	LH0243909	 	
Sample Date	27 Feb 2024	 	
Machine Hours	5666	 	
Oil Hours	0	 	
Oil Changed	Changed	 	
Sample Status	NORMAL	 	
•			

OIL CONDITION

Visc @ 40°C

cSt 0 164

	TAMINA	FION		
Water	%	NEG	 	
Silicon	ppm	0 21	 	
Sodium	ppm	0 22	 	
Potassium	ppm	03	 	

Ä				
WEA	R METALS			
Iron	ppm	266	 	
Copper	ppm	0 48	 	
Lead	ppm	0	 	
Tin	ppm	<mark>○</mark> <1	 	
Aluminum	ppm	2	 	
Chromium	ppm	01	 	
Molybdenum	ppm	0	 	
Nickel	ppm	<mark>○</mark> <1	 	
Titanium	ppm	○ <1	 	
Silver	ppm	0	 	
Manganese	ppm	5	 	
Vanadium	ppm	0	 	

	JIIVES			
Calcium	ppm	9 1	 	
Magnesium	ppm	0 5	 	
Zinc	ppm	58	 	
Phosphorus	ppm	2118	 	
Barium	ppm	0 🔘	 	
Boron	ppm	0 ()	 	





LIEBHERR EQUIPMENT SOURCE

4100 CHESTNUT AVENUE NEWPORT NEWS, VA US 23607 Contact: LUKE APPLEBY Lucas.Appleby@liebherr.com T: F: (757)298-8700

Diagnosis

Resample at the next service interval to monitor.All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:	LIEBHERRUS
Unique No:	10915846
Signed:	Wes Davis
Report Date:	08 Mar 2024

Contact/Location: LUKE APPLEBY - LIEBHERRUS

LEBHERR CONSTRUCTION EQUIPMENT



Ø

Ferrous Alloys

GRAPHS



