LIEBHERR

CONSTRUCTION EQUIPMENT

LIEBHERR R944 042563-194 - Splitter Box

Sample No: LH0243874

Oil Type: LIEBHERR GEAR BASIC 90 LS

5					
U SAM	APLE INFO	ORMATION			
Sample Number		LH0243874	LH0229404	LHMC93582	
Sample Date		29 Feb 2024	03 Oct 2022	29 Dec 2015	
Machine Hours		29512	28033	15560	
Oil Hours		0	2000	1000	
Oil Changed		Changed	N/A	Changed	
Sample Status		ABNORMAL	ABNORMAL	NORMAL	
A					
OIL	CONDITIO	ON			
Visc @ 40°C	cSt	200	O 200	227.4	
-1		O 11	0		
CON		TIAN			
	ITAMINA	ATION			
Water	%	NEG	0.162	NEG	
Silicon	ppm	13	O 18	4	
Sodium	ppm	8	6	<1	
Potassium	ppm	4	O 1	4	
(O) WE	AR META	LS			
Iron	ppm	365	O 214	3 5	
Copper	ppm	2	O <1	3	
Lead	ppm	0	O 0	O <1	
Tin	ppm	O <1	O 0	O 0	
Aluminum	ppm	4	O 11	O <1	
Chromium	ppm	2	O 2	O <1	
Molybdenum	ppm	0 0	O <1	<1	
Nickel	ppm	() <1	O 0	0	
Titanium	ppm	<1	<1	0	
Silver	ppm	0	0	0	
Manganese	ppm	4	4	<1	
Vanadium	ppm	0	0	0	

 \bigcirc 0

 \bigcirc 5

97

 \bigcirc 0

14

2017

44

3

94

568

029



LIEBHERR EQUIPMENT SOURCE

4100 CHESTNUT AVENUE NEWPORT NEWS, VA US 23607

Contact: LUKE APPLEBY Lucas.Appleby@liebherr.com

T:

F: (757)298-8700

Diagnosis

The oil change at the time of sampling has been noted. No corrective action is recommended at this time. Resample at the next service interval to monitor. Gear wear is indicated. All other component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:LIEBHERRUSUnique No:10915852Signed:Don BaldridgeReport Date:11 Mar 2024

7

4

0

20

138

2132

ADDITIVES

mqq

ppm

ppm

ppm

ppm

ppm

Calcium

Zinc

Barium

Boron

Magnesium

Phosphorus

CONSTRUCTION EQUIPMENT





GRAPHS

