LIEBHERR

CONSTRUCTION EQUIPMENT

LIEBHERR LH50 Timber 136525-1474 - Gearbox

Sample No: LH0268713

Oil Type: LIEBHERR MOTOROIL 5W30



CONTAMINATION								
Water	%	NEG						
Silicon	ppm	5	***	***				
Sodium	ppm	15						
Potassium	ppm	1						

(O) WE				
WEA	IR METAI	LS		
Iron	ppm	76	 	
Copper	ppm	72	 	
Lead	ppm	1	 	
Tin	ppm	2	 	
Aluminum	ppm	2	 	
Chromium	ppm	○ <1	 	
Molybdenum	ppm	0	 	
Nickel	ppm	0	 	
Titanium	ppm	0	 	
Silver	ppm	0	 	
Manganese	ppm	18	 	
Vanadium	ppm	<1	 	

ADDITIVES							
Calcium	ppm	2007					
Magnesium	ppm	415					
Zinc	ppm	858					
Phosphorus	ppm	887					
Barium	ppm	0					
Boron	ppm	73					



LIEBHERR EQUIPMENT SOURCE

8200 FAYETTEVILLE ROAD RALEIGH, NC

US 27603

Contact: TAYLOR BLALOCK taylor.blalock@liebherr.com

T: (757)718-0491 F: (919)329-0084

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:LIEBHERRNCUnique No:10922591Signed:Sean FeltonReport Date:12 Mar 2024

Submitted By: TAYLOR BLALOCK

CONSTRUCTION EQUIPMENT





GRAPHS

