CONSTRUCTION EQUIPMENT

LIEBHERR LH50 TIMBER 1474-138132 - Splitter Box

Sample No: LH0267629

Oil Type: LIEBHERR GEAR BASIC 90 LS

SAMPLE INFORMATION

Sample Number	LH0267629	 	
Sample Date	14 Mar 2024	 	
Machine Hours	3100	 	
Oil Hours	1000	 	
Oil Changed	Changed	 	
Sample Status	NORMAL	 	

OIL CONDITION

Visc @ 40°C

-

cSt 0 191

Water	%	NEG				
Silicon	ppm	01				
Sodium	ppm	3				
Potassium	ppm	0 2				

WEA WEA	R META	LS		
Iron	ppm	0 49	 	
Copper	ppm	0 5	 	
Lead	ppm	0	 	
Tin	ppm	0 ()	 	
Aluminum	ppm	02	 	
Chromium	ppm	<mark></mark> <1	 	
Molybdenum	ppm	0 🔘	 	
Nickel	ppm	0 🔘	 	
Titanium	ppm	0	 	
Silver	ppm	0	 	
Manganese	ppm	01	 	
Vanadium	ppm	0	 	

0

	DITIVES			
Calcium	ppm	1 9	 	
Magnesium	ppm	0 4	 	
Zinc	ppm	0 26	 	
Phosphorus	ppm	0 1476	 	
Barium	ppm	0 🔘	 	
Boron	ppm	0 🔘	 	





LIEBHERR EQUIPMENT SOURCE

8200 FAYETTEVILLE ROAD RALEIGH, NC US 27603 Contact: TAYLOR BLALOCK taylor.blalock@liebherr.com T: (757)718-0491 F: (919)329-0084

Diagnosis

Resample at the next service interval to monitor.All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:LIEBHERRNCUnique No:10928647Signed:Sean FeltonReport Date:19 Mar 2024

Report Id: LIEBHERRNC [WUSCAR] 06119814 (Generated: 03/19/2024 14:07:18) Rev: 1

Submitted By: TAYLOR BLALOCK





Ferrous Alloys

GRAPHS

Ö

