# LIEBHERR

## **CONSTRUCTION EQUIPMENT**

### LIEBHERR LH30M 1253-144576 - Diesel Engine

Sample No: LH0276413

Oil Type: PETRO CANADA DURON UHP 5W40

SAMPLE INFORMATION						
Sample Number	LH0276413	LH0276410				
Sample Date	25 Mar 2024	10 Oct 2023				
Machine Hours	1155	540				
Oil Hours	0	0				
Oil Changed	Changed	Changed				
Sample Status	ATTENTION	ABNORMAL				
<b>A</b>						

OIL CONDITION						
Visc @ 100°C	cSt	<u> </u>	O 11.4			
Base Number (BN)	mg KOH/g	<b>7.8</b>	O 5.1			
Oxidation (PA)	%	98	200			
- 1 min						

CONTAMINATION					
Water	%	NEG	NEG		
Soot %	%	<b>0.1</b>	0.1		
Nitration (PA)	%	79	102		
Sulfation (PA)	%	60	108		
Glycol	%	NEG	NEG		
Fuel	%	<b>1.1</b>	<1.0		
Silicon	ppm	<b>8</b>	<b>1</b> 5		
Sodium	ppm	<b>0</b>	<b>0</b>		
Potassium	ppm	<b>2</b>	<b>5</b>		

WEA	R METALS			
Iron	ppm	07	O 13	 
Copper	ppm	<b>57</b>	270	 
Lead	ppm	01	02	 
Tin	ppm	<b>2</b>	O 1	 
Aluminum	ppm	<b>1</b>	O 2	 
Chromium	ppm	<b>1</b>	O <1	 
Molybdenum	ppm	<b>46</b>	<b>46</b>	 
Nickel	ppm	<b>0</b> <1	0	 
Titanium	ppm	<1	<1	 
Silver	ppm	<b>0</b>	O 0	 
Manganese	ppm	<b>○</b> <1	O <1	 
Vanadium	ppm	<1	0	 

ADDI	TIVES			
Calcium	ppm	<b>1288</b>	O 1322	 
Magnesium	ppm	<b>844</b>	○ 892	 
Zinc	ppm	<b>877</b>	○ 850	 
Phosphorus	ppm	<b>763</b>	O 686	 
Barium	ppm	<b>4</b>	19	 
Boron	ppm	<b>114</b>	O 84	 



# **TRAM CONSTRUCTION** 9279 E KY 8

GARRISON, KY US 41141

Contact: Service Manager

T: F:

#### Diagnosis

Oil and filter change at the time of sampling has been noted. Resample at the next service interval to monitor. All component wear rates are normal. Fuel content negligible. There is no indication of any contamination in the oil. The oil viscosity is lower than normal. The BN result indicates that there is suitable alkalinity remaining in the oil. Confirm oil type.

Depot:TRAGARLHUnique No:10949837Signed:Jonathan HesterReport Date:02 Apr 2024

### Submitted By: ?

# LIEBHERR

CONSTRUCTION EQUIPMENT





#### **GRAPHS**

