LIEBHERR

CONSTRUCTION EQUIPMENT

LIEBHERR LH110 1227-155752 - Swing Drive

Sample No: LH0280586 Oil Type: SAE 30W

SAMPLE INFORMATION							
Sample Number	LH0280586	LH0280575	LH0280564				
Sample Date	19 Mar 2024	20 Feb 2024	11 Jan 2024				
Machine Hours	1544	1022	507				
Oil Hours	0	0	0				
Oil Changed	Not Changd	Changed	Not Changd				
Sample Status	ATTENTION	ATTENTION	NORMAL				

oup.o otatao		/ · · · · = · · · · · · · · · · · · · ·			
OIL CO	NDITION				
Visc @ 40°C	cSt	176	179	180	

CONTAMINATION							
Water	%	NEG	NEG	NEG			
Silicon	ppm	6	O 7	5			
Sodium	ppm	3	3	4			
Potassium	ppm	2	O <1	O 2			

WEA	R METALS				
Iron	ppm	265	O 297	O 203	
Copper	ppm	118	O 119	○ 67	
Lead	ppm	() <1	O 1	O <1	
Tin	ppm	11	0 8	5	
Aluminum	ppm	2	O 1	1	
Chromium	ppm	1	O <1	O <1	
Molybdenum	ppm	1	0	0	
Nickel	ppm	○ <1	0	O <1	
Titanium	ppm	0	0	0	
Silver	ppm	0	0	0	
Manganese	ppm	2	O 2	2	
Vanadium	ppm	<1	<1	0	

vanadium	ppm	<1	<1	0			
ADDITIVES							
Calcium	ppm	98	O 119	46			
Magnesium	ppm	0	<1	2			
Zinc	ppm	45	3 9	16			
Phosphorus	ppm	2091	O 2188	1879			
Barium	ppm	1	3	4			
Boron	ppm	9	6	5			



KINDER MORGAN 4301 IVERSON TRINITY, AL US 35601

Contact: CHIP OAKES

T: (256)350-0006 F: (256)355-5250

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The oil viscosity is higher than normal. This plus the additive levels indicates the addition of a different brand, or type of oil. Confirm oil type.

Depot: KINTRI
Unique No: 10950647
Signed: Don Baldridge
Report Date: 01 Apr 2024





GRAPHS

