LIEBHERR

CONSTRUCTION EQUIPMENT

LIEBHERR LH110 1227-155752 - Rear Right Wheel Hub

Sample No: LH0280590

Oil Type: GEAR OIL SAE 80W90

_ _						
SAMPLEINFORMATION						
Sample Number	LH0280590	LH0280579	LH0280568			
Sample Date	19 Mar 2024	20 Feb 2024	11 Jan 2024			
Machine Hours	1544	1022	507			
Oil Hours	0	0	0			
Oil Changed	Not Changd	Changed	Not Changd			
Sample Status	ATTENTION	NORMAL	NORMAL			

OILCO	NDITION				
Visc @ 40°C	cSt	99.6	149	150	
_					

CONT	AMINATIO	ON			
Water	%	NEG	NEG	NEG	
Silicon	ppm	4	0 8	O 7	
Sodium	ppm	0 <1	O 2	4	
Potassium	ppm	1	O 0	1	

WE!	AR META	LS			
Iron	ppm	39	5 5	3 7	
Copper	ppm	10	O 25	1 9	
Lead	ppm	0	 <1	O <1	
Tin	ppm	2	O 0	O <1	
Aluminum	ppm	○ <1	<1	O <1	
Chromium	ppm	○ <1	 <1	O 0	
Molybdenum	ppm	2	 <1	0	
Nickel	ppm	○ <1	O 0	O <1	
Titanium	ppm	0	0	O 0	
Silver	ppm	0	<1	0	
Manganese	ppm	○ <1	O 2	2	
Vanadium	ppm	<1	<1	0	

ADDI	TIVES				
Calcium	ppm	177	O 99	107	
Magnesium	ppm	4	O 0	2	
Zinc	ppm	93	O 24	23	
Phosphorus	ppm	469	O 1365	1246	
Barium	ppm	0	O <1	2	
Boron	ppm	2	O 4	5	



KINDER MORGAN 4301 IVERSON TRINITY, AL US 35601

Contact: CHIP OAKES

T: (256)350-0006 F: (256)355-5250

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The oil viscosity is lower than normal. The condition of the oil is acceptable for the time in service.

Depot: KINTRI
Unique No: 10950651
Signed: Don Baldridge
Report Date: 01 Apr 2024

LIEBHERR

CONSTRUCTION EQUIPMENT





GRAPHS

