LIEBHERR



LIEBHERR LH80M 1218-157090 - Front Left Wheel Hub

Sample No: LH0282898

Oil Type: GEAR OIL SAE 80W90

5					
SAMPLEINFORMATION					
Sample Number		LH0282898			
Sample Date		19 Mar 2024			
Machine Hours		545			
Oil Hours		0			
Oil Changed		Not Changd			
Sample Status		NORMAL			
OIL CONDITION					
Visc @ 40°C	cSt	161			

CONTAMINATION						
Water	%	NEG				
Silicon	ppm	26				
Sodium	ppm	8				
Potassium	ppm	O <1				

₩EA	R META	LS		
Iron	ppm	113	 	
Copper	ppm	6	 	
Lead	ppm	0	 	
Tin	ppm	1	 	
Aluminum	ppm	3	 	
Chromium	ppm	<1	 	
Molybdenum	ppm	<1	 	
Nickel	ppm	○ <1	 	
Titanium	ppm	<1	 	
Silver	ppm	0	 	
Manganese	ppm	2	 	
Vanadium	ppm	<1	 	

variadium	ppm	<				
ADDITIVES						
Calcium	ppm	68				
Magnesium	ppm	0				
Zinc	ppm	21				
Phosphorus	ppm	1249				
Barium	ppm	0				
Boron	ppm	0 <1				



KINDER MORGAN

4301 IVERSON TRINITY, AL US 35601

Contact: RICKY JOHNSON ricky_johnson@kindermorgan.com

T:

F: (256)355-5250

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot: KINTRI
Unique No: 10950659
Signed: Wes Davis
Report Date: 28 Mar 2024

LIEBHERR

CONSTRUCTION EQUIPMENT





GRAPHS

