LIEBHERR

CONSTRUCTION EQUIPMENT

LIEBHERR LH30M 1253-144576 - Rear Right Wheel Hub

Sample No: LH0276421
Oil Type: {unknown}

5			
SAMPI	LE INFORMATION		
Sample Number	LH0276421	 	
Sample Date	21 Mar 2024	 	
Machine Hours	1155	 	
Oil Hours	0	 	
Oil Changed	Not Changd	 	
Sample Status	NORMAL	 	
A			

Transport of the Parket
V III
10 TO
d II

TRAM CONSTRUCTION 9279 E KY 8 GARRISON, KY

GARRISON, KY US 41141

Contact: Service Manager

T: F:

OIL CO	ONDITION			
Visc @ 40°C	cSt	○ 98.5	 	

CONTAMINATION Water % NEG -- -- -- Silicon ppm 6 -- -- -- Sodium ppm 10 -- -- -- Potassium ppm 1 -- -- --

WEA	R META	LS		
Iron	ppm	23	 	
Copper	ppm	6	 	
Lead	ppm	<1	 	
Tin	ppm	2	 	
Aluminum	ppm	() <1	 	
Chromium	ppm		 	
Molybdenum	ppm	<1	 	
Nickel	ppm	○ <1	 	
Titanium	ppm	0	 	
Silver	ppm	0	 	
Manganese	ppm	2	 	
Vanadium	ppm	<1	 	

Titanium	ppm	0	 	
Silver	ppm	0	 	
Manganese	ppm	2	 	
Vanadium	ppm	<1	 	
ADD	ITIVES			
Calcium	ppm	1541	 	
		1541 3	 	
Calcium	ppm	-		
Calcium Magnesium	ppm ppm	3	 	
Calcium Magnesium Zinc	ppm ppm ppm	3 615	 	

Diagnosis

Resample at the next service interval to monitor. Please specify the brand, type, and viscosity of the oil on your next sample.All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:TRAGARLHUnique No:10950666Signed:Wes DavisReport Date:28 Mar 2024

LIEBHERR

CONSTRUCTION EQUIPMENT





GRAPHS

