**CONSTRUCTION EQUIPMENT** 

## LIEBHERR LH30M 1253-144576 - Front Right Wheel Hub

Sample No: LH0276419 Oil Type: {unknown}

<b>=</b>								
SAMPLE INFORMATION								
Sample Number		LH0276419						
Sample Date		21 Mar 2024						
Machine Hours		1155						
Oil Hours		0						
Oil Changed		Not Changd						
Sample Status		NORMAL						
A								

## US 41141 Contact: Service Manager T:

### **OIL CONDITION** Visc @ 40°C 90.9 CONTAMINATION Water **NEG** Silicon ppm **6** Sodium **18** ppm

Potassium	ppm	<b>○</b> <1	 	
<b>**</b>				
₩EA	R METAL	6		
THE TYPE	IK IVIE I PAL	13		
Iron	ppm	<b>86</b>	 	
Copper	ppm	<b>25</b>	 	
Lead	ppm	<b>0</b>	 	
Tin	ppm	2	 	
Aluminum	ppm	<b></b> <1	 	
Chromium	ppm	<b>1</b>	 	
Molybdenum	ppm	<1	 	
Nickel	ppm	<b>○</b> <1	 	
Titanium	ppm	<1	 	
Silver	ppm	0	 	
Manganese	ppm	2	 	
Vanadium	ppm	<1	 	

variaululli	ppiii	<b>SI</b>						
ADDITIVES								
Calcium	ppm	1701						
Magnesium	ppm	6						
Zinc	ppm	659						
Phosphorus	ppm	770						
Barium	ppm	0						
Boron	ppm	71						



## Diagnosis

F:

9279 E KY 8 GARRISON, KY

Resample at the next service interval to monitor. Please specify the brand, type, and viscosity of the oil on your next sample.All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot: **TRAGARLH** Unique No: 10950667 Signed: Wes Davis **Report Date:** 28 Mar 2024

# LIEBHERR

CONSTRUCTION EQUIPMENT





## **GRAPHS**

