LIEBHERR

CONSTRUCTION EQUIPMENT

LIEBHERR A924C 056977-1049 - Rear Differential

Sample No: LH06132474

Oil Type: GEAR OIL SAE 90

Sample Information						
Sample Number	LH06132474	LHMC79123	LH03107867			
Sample Date	21 Mar 2024	05 Oct 2016	18 Jul 2012			
Machine Hours	16385	10210	2162			
Oil Hours	0	0	0			
Oil Changed	N/A	Not Changd	Changed			
Sample Status	NORMAL	NORMAL	NORMAL			

Campio Cialao	HOIMAL	14011111111	140111111111	
Oil Condition	on			
Visc @ 40°C cSt	122	O 109.6	162.9	

Conta	ımination				
Water	%	NEG	NEG	NEG	
Silicon	ppm	8	6	5	
Sodium	ppm	3	3	O <1	
Potassium	ppm	3	O <1	O <1	

10					
Wea	r Metals				
Iron	ppm	86	18	O 11	
Copper	ppm	2	O 2	O 2	
Lead	ppm	0	0	O 0	
Tin	ppm	0 <1	0	O <1	
Aluminum	ppm	2	O 2	0	
Chromium	ppm	0 <1	O <1	O <1	
Molybdenum	ppm	0 <1	O <1	0	
Nickel	ppm	2	O <1	<1	
Titanium	ppm	0	<1	0	
Silver	ppm	0	0	0	
Manganese	ppm	3	O <1	1	
Vanadium	ppm	0	0	0	

Additives							
Calcium	ppm	31	O 52	162			
Magnesium	ppm	3	O 1	<1			
Zinc	ppm	27	○ 32	82			
Phosphorus	ppm	528	O 1218	2115			
Barium	ppm	0	 <1	6			
Boron	ppm	35	O 146	1			



RECO EQUIPMENT INC.

1615 JP HENESSY DRIVE LAVERGNE, TN US 37086

Contact: KEN FISCHER

T: (615)610-7326

F:

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:RECLAVUnique No:10951939Signed:Wes DavisReport Date:01 Apr 2024

CONSTRUCTION EQUIPMENT





Graphs

