# LIEBHERR

**CONSTRUCTION EQUIPMENT** 

# LIEBHERR A924C056977-1049-Transmission

Sample No: LH06132555
Oil Type: {unknown}



ouripic otatus		HOHIMAL	I VOI LIVI/ LL	TAOT TIVIT TE	
Oil Co	ondition				
Visc @ 40°C	cSt	<b>63.2</b>	79.12	<b>59.95</b>	
- <del></del>					

Contamination							
Water	%	NEG	NEG	NEG			
Silicon	ppm	<b>9</b>	0 8	<b>4</b>			
Sodium	ppm	<b>10</b>	<b>18</b>	○ 33			
Potassium	ppm	<b>2</b>	O 0	<b>1</b>			

ır Metals	;			
ppm	<b>33</b>	○ 32	<b>O</b> 57	
ppm	<b>49</b>	O 29	<b>37</b>	
ppm	<b>0</b>	<b>O</b> 0	O <1	
ppm	<b>1</b>	0	O 1	
ppm	<b>4</b>	<b>4</b>	O 2	
ppm	<b>0</b>	<b>O</b> <1	O <1	
ppm	59	76	23	
ppm	<1	<1	O 1	
ppm	<1	0	0	
ppm	0	0	<1	
ppm	3	8	27	
ppm	<1	0	0	
	ppm	ppm	ppm       33       32         ppm       49       29         ppm       0       0         ppm       1       0         ppm       4       4         ppm       0       <1	ppm       33       32       57         ppm       49       29       37         ppm       0       0       <1

Additives						
Calcium	ppm	1402	1503	1645		
Magnesium	ppm	521	360	537		
Zinc	ppm	1085	1162	1323		
Phosphorus	ppm	957	1053	1292		
Barium	ppm	0	0	1		
Boron	ppm	181	432	11		



#### RECO EQUIPMENT INC. 1615 JP HENESSY DRIVE LAVERGNE, TN US 37086

Contact: KEN FISCHER

T: (615)610-7326

F:

### Diagnosis

Resample at the next service interval to monitor. Please specify the brand, type, and viscosity of the oil on your next sample.All component wear rates are normal. There is no indication of any contamination in the fluid. The condition of the fluid is acceptable for the time in service.


Depot: RECLAV
Unique No: 10952020
Signed: Sean Felton
Report Date: 02 Apr 2024

CONSTRUCTION EQUIPMENT





## **Graphs**



Report Id: RECLAV [WUSCAR] 06132555 (Generated: 04/05/2024 04:07:47) Rev: 1

Contact/Location: WEBCHECK IN LEC0081 - KEN FISCHER - RECLAV