LIEBHERR


CONSTRUCTION EQUIPMENT

LIEBHERR R956 045059-1476 - Hydraulic System

Sample No: LHMC93500

Oil Type: LIEBHERR HYDRAULIC HVI

5								
Sample Information								
Sample Number		LHMC93500						
Sample Date		29 Mar 2024						
Machine Hours		7962						
Oil Hours		2						
Oil Changed		Changed						
Sample Status		NORMAL						
Oil Condition								
Visc @ 40°C	cSt	54.8						
Acid Number (AN)	mg KOH/g	0.54						
Contamination								
Water	%	NEG						
Particles >4µm		12741						
Particles >6µm		1206						
Particles >14µm		61						
ISO 4406:1999 (c)		21/17/13						
Silicon	ppm	2						
Sodium	ppm	0						
Potassium	ppm	2						



Additives								
Calcium	ppm	○ 805						
Magnesium	ppm	6						
Zinc	ppm	420						
Phosphorus	ppm	383						
Barium	ppm	0						
Boron	ppm	0						





BANE MACHINERY INC

10505 N FREEWAY FORT WORTH, TX US 76177

Contact: BEN WILLIAMS bwilliams@banemachinery.com

T: (817)948-9460

F:

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The amount and size of particulates present in the system are acceptable. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.

Depot:BANFORUnique No:10992293Signed:Angela BorellaReport Date:24 Apr 2024

LIEBHERR







Graphs

