LIEBHERR

CONSTRUCTION EQUIPMENT

LIEBHERR LH60M 121879-1217 - Front Differential

Sample No: LH0273593

Additives

mqq

ppm

ppm

ppm

ppm

ppm

Calcium

Zinc

Barium

Boron

Magnesium

Phosphorus

Oil Type: LIEBHERR GEAR BASIC 90 LS

ple Infor	mation			
	LH0273593	LH0268863		
	12 Apr 2024	27 Feb 2024		
	7725	7442		
	7725	0		
	Not Changd	Changed		
	NORMAL	ABNORMAL		
ondition	l			
cSt	185	O 185		
aminati	on			
%	NEG	NEG		
ppm	2	4		
ppm	1	6		
ppm	O <1	O 1		
ı <mark>r Metal</mark> :	,			
ppm	5	O 29		
ppm	12	134		
ppm	() <1	O <1		
ppm	0 <1	O <1		
ppm	2	O 1		
ppm	O <1	O 0		
ppm	() <1	O 0		
ppm	O <1	O <1		
ppm	<1	0		
ppm	0	0		
ppm	0 <1	O 2		
ppm	<1	0		
	ondition cSt cSt cSt cSt cSt cSt cSt cSt	12 Apr 2024 7725 7725 Not Changd NORMAL Ondition cSt	LH0273593 LH0268863 12 Apr 2024 27 Feb 2024 7725 7442 7725 0 Not Changed NORMAL ABNORMAL	LH0273593

02

0 87

1213

339

 \bigcirc 0



LIEBHERR EQUIPMENT SOURCE

4100 CHESTNUT AVENUE NEWPORT NEWS, VA US 23607

Contact: LUKE APPLEBY

Lucas.Appleby@liebherr.com T:

1:

F: (757)298-8700

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot: LIEBHERRUS
Unique No: 10994013
Signed: Wes Davis
Report Date: 25 Apr 2024

12

4

11

27

6

2198

LIEBHERR CONSTRUCTION EQUIPMENT





Graphs

