CONSTRUCTION EQUIPMENT

LIEBHERR LH60M 1204-74217 - Rear Left Wheel Hub

Sample No: LH06163743

Oil Type: GEAR OIL SAE 80W90

Sample Information

Sample Number	LH06163743	LHMC121031	LHMC92423	LHMC80517
Sample Date	09 Apr 2024	10 Aug 2017	31 Mar 2017	24 May 2016
Machine Hours	14693	8752	7383	4556
Oil Hours	1000	0	0	0
Oil Changed	Changed	Changed	N/A	Changed
Sample Status	NORMAL	NORMAL	NORMAL	NORMAL
Oil Condition				
Visc @ 40°C cSt	0 128	0 186.3	0 197.3	0 184.3

Con	taminati	ion				
Water	%	NEG	NEG	NEG	NEG	
Silicon	ppm	0 2	○ 5	0 4	5	
Sodium	ppm	○ <1	2	2	2	
Potassium	ppm	0	0 2	01	0 2	

Ä					
Weal	Metals				
Iron	ppm	06	142	126	128
Copper	ppm	02	37	35	32
Lead	ppm	0	○ <1	0	0
Tin	ppm	○ <1	○ <1	0	0
Aluminum	ppm	0	2	01	2
Chromium	ppm	○ <1	2	2	02
Molybdenum	ppm	02	0	0	0
Nickel	ppm	0	○ <1	01	01
Titanium	ppm	0	○ <1	○ <1	○ <1
Silver	ppm	0	0	0	0
Manganese	ppm	○ <1	2	2	2
Vanadium	ppm	0	0	0	0

0 **Additives** Calcium 074 ppm 8 6 $\bigcirc 7$ Magnesium 02 $\bigcirc 1$ $\bigcirc 2$ ○ <1 ppm 0 22 Zinc 0 22 021 021 ppm Phosphorus ppm 0740 0 972 0 877 0 1066 Barium 0 241 0 282 ppm 0 333 Boron ppm 0 54 0 27 \bigcirc 3 1



MIDDLE RIVER MARINE

1771 SOUTH TORRENCE AVE CHICAGO, IL US 60617 Contact: Scott Molitor scottmolitor@gomiddleriver.com T: F:

Diagnosis

Resample at the next service interval to monitor. Please specify the brand, type, and viscosity of the oil on your next sample.All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.


Depot:MIDCHIILUnique No:11004462Signed:Wes DavisReport Date:30 Apr 2024Contact/Location: Scott Molitor - MIDCHIIL







Graphs



Report Id: MIDCHIIL [WUSCAR] 06163743 (Generated: 05/03/2024 21:52:42) Rev: 1