LIEBHERR

CONSTRUCTION EQUIPMENT

LIEBHERR LH30M 1253-143895 - Rear Differential

Sample No: LH0276316
Oil Type: {unknown}

Oil Condition

cSt

96.6

Visc @ 40°C





TRAM CONSTRUCTION

9279 E KY 8 GARRISON, KY US 41141

Contact: Service Manager

T: F:

Conta	Contamination					
Water	%	NEG				
Silicon	ppm	3				
Sodium	ppm	7				
Potassium	ppm	0				

Wear	Metals			
Iron	ppm	9	 	
Copper	ppm	0 <1	 	
Lead	ppm	0	 	
Tin	ppm	0 <1	 	
Aluminum	ppm	0 <1	 	
Chromium	ppm	0	 	
Molybdenum	ppm	0	 	
Nickel	ppm	0	 	
Titanium	ppm	0	 	
Silver	ppm	0	 	
Manganese	ppm	1	 	
Vanadium	ppm	0	 	

Manganese	ppm	ı			
Vanadium	ppm	0			
Additives					
Calcium	ppm	1310			
Magnesium	ppm	1			
Zinc	ppm	551			
Phosphorus	ppm	743			
Barium	ppm	0			
Boron	ppm	40			

Diagnosis

Resample at the next service interval to monitor. Please specify the brand, type, and viscosity of the oil on your next sample.All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot: TRAGARLH
Unique No: 11004494
Signed: Wes Davis
Report Date: 30 Apr 2024

LIEBHERR

CONSTRUCTION EQUIPMENT





Graphs

