## LIEBHERR

**CONSTRUCTION EQUIPMENT** 

### - Front Right Wheel Hub

Sample No: LH06176293
Oil Type: {unknown}



Campic Claids		NOTHINAL						
Oilc	Oil Condition							
Visc @ 40°C	cSt	<b>153</b>						

Conte	amination			
Water	%	NEG	 	
Silicon	ppm	<b>26</b>	 	
Sodium	ppm	<b>6</b>	 	
Potassium	ppm	<b>3</b>	 	

Wed	ır Metals			
Iron	ppm	<b>78</b>	 	
Copper	ppm	<b>15</b>	 	
Lead	ppm	<b>0</b>	 	
Tin	ppm	<b>0</b>	 	
Aluminum	ppm	<b>2</b>	 	
Chromium	ppm	<b>0</b> 0	 	
Molybdenum	ppm	0	 	
Nickel	ppm	<b>0</b> 0	 	
Titanium	ppm	<1	 	
Silver	ppm	0	 	
Manganese	ppm	4	 	
Vanadium	ppm	0	 	

56			
0			
<1			
1381			
0			
25			
	0 <1 1381 0	0 <1 1381 0	0 <1 1381



SADOFF 2055 SOUTH 108TH STREET MILWAUKEE, WI US 53227 Contact: RAY SCHMIDT

T: (414)541-8700 F: (414)541-1892

#### Diagnosis

Resample at the next service interval to monitor. Please specify the brand, type, and viscosity of the oil on your next sample. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot: SADMIL
Unique No: 11022346
Signed: Sean Felton
Report Date: 14 May 2024

# LIEBHERR

## CONSTRUCTION EQUIPMENT





#### **Graphs**

