LIEBHERR

CONSTRUCTION EQUIPMENT

LIEBHERR LH80M 1218-157090 - Rear Right Wheel Hub

Sample No: LH0282890

Vanadium

Calcium

Zinc

Barium

Boron

Magnesium

Phosphorus

ppm

mqq

ppm

ppm

ppm

ppm

ppm

Additives

Oil Type: GEAR OIL SAE 80W90

5				
Samp	<mark>le Inform</mark> c	ition		
Sample Number		LH0282890	LH0282901	
Sample Date		19 Apr 2024	19 Mar 2024	
Machine Hours		997	545	
Oil Hours		0	0	
Oil Changed		Changed	Not Changd	
Sample Status		NORMAL	NORMAL	
A				
Oil Co	ndition			
Visc @ 40°C	cSt	O 141	O 139	
-1			0	
Comba	mination			
Conta	mination			
Water	%	NEG	NEG	
Silicon	ppm	10	10	
Sodium	ppm	2	O 2	
Potassium	ppm	O <1	O <1	
Wear	Metals			
ron	ppm	36	O 34	
Copper	ppm	0 11	O 10	
_ead	ppm	00	00	
Tin	ppm	0 <1	01	
Aluminum	ppm	00	0 <1	
Chromium	ppm	0 <1	0 <1	
Molybdenum	ppm	00	0 <1	
Nickel	ppm	00	0 <1	
	1.1		_	
i itanium	mag	0 0	0	
Titanium Silver	ppm	0	0	

0 19

0

3



KINDER MORGAN

4301 IVERSON TRINITY, AL US 35601

Contact: RICKY JOHNSON ricky_johnson@kindermorgan.com

T:

F: (256)355-5250

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:KINTRIUnique No:11029287Signed:Wes DavisReport Date:14 May 2024

118

5

25

2

6

1406

LIEBHERR

CONSTRUCTION EQUIPMENT





Graphs

