

LIEBHERR

CONSTRUCTION EQUIPMENT



LIEBHERR LH110 1227-155752 - Rear Left Wheel Hub

Sample No: LH0280589

Oil Type: GEAR OIL SAE 80W90



KINDER MORGAN
4301 IVERSON
TRINITY, AL
US 35601
Contact: CHIP OAKES

T: (256)350-0006
F: (256)355-5250



Sample Information

Sample Number	LH0280589	LH0280589	LH0280578	LH0280567
Sample Date	18 Apr 2024	19 Mar 2024	20 Feb 2024	11 Jan 2024
Machine Hours	1980	1544	1022	507
Oil Hours	0	0	0	0
Oil Changed	Changed	Not Changd	N/A	Not Changd
Sample Status	ATTENTION	ATTENTION	NORMAL	NORMAL



Oil Condition

Visc @ 40°C	cSt	96.2	99.9	150	173



Contamination

Water	%	NEG	NEG	NEG	NEG
Silicon	ppm	5	4	8	8
Sodium	ppm	<1	<1	2	5
Potassium	ppm	0	<1	0	2



Wear Metals

Iron	ppm	49	41	72	20
Copper	ppm	14	11	28	0
Lead	ppm	0	0	<1	0
Tin	ppm	0	1	0	<1
Aluminum	ppm	1	<1	<1	<1
Chromium	ppm	<1	<1	<1	0
Molybdenum	ppm	1	2	<1	0
Nickel	ppm	0	<1	0	<1
Titanium	ppm	<1	0	0	0
Silver	ppm	0	0	0	0
Manganese	ppm	1	<1	2	<1
Vanadium	ppm	0	<1	<1	0



Additives

Calcium	ppm	187	175	107	136
Magnesium	ppm	4	3	0	2
Zinc	ppm	104	93	23	18
Phosphorus	ppm	491	486	1445	1345
Barium	ppm	0	0	<1	<1
Boron	ppm	0	2	6	5

Diagnosis

The oil change at the time of sampling has been noted. Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The oil viscosity is lower than normal. Confirm oil type.

Depot: KINTRI
Unique No: 11031839
Signed: Don Baldrige
Report Date: 17 May 2024



Graphs

