LIEBHERR

CONSTRUCTION EQUIPMENT



Sample No: LH0273818

Oil Type: LIEBHERR 15W40

Sample Number		LH0273818	 	
Sample Date		21 May 2024	 	
Machine Hours		503	 	
Oil Hours		503	 	
Oil Changed		Changed	 	
Sample Status		ABNORMAL	 	
<u> </u>				
OilCo	ndition			
		0.44.7		
Visc @ 100°C	cSt	0 11.7	 	
Base Number (BN)	-	3.9	 	
Oxidation (PA)	%	189	 	
	_			
Conta	mination			
Water	%	NEG	 	
Soot %	%	0.1	 	
Nitration (PA)	%	96	 	
Sulfation (PA)	%	103	 	
Glycol	%	NEG	 	
Fuel	%	0.9	 	
Silicon	ppm	9	 	
Sodium	ppm	3	 	
Potassium	ppm	O <1	 	
(O) Woom	Metals			
lron -	ppm	13	 	
Copper	ppm	278	 	
Lead	ppm	4	 	
Γin	ppm	2	 	
Aluminum	ppm	4	 	
Chromium	ppm	2	 	
Molybdenum	ppm	43	 	
Vickel	ppm	0	 	
Titanium	ppm	0	 	
Silver	ppm	○ <1	 	
Manganese	ppm	1	 	
Vanadium	ppm	<1	 	



RECO EQUIPMENT INC

2455 MAREMONT PKWY LOUDON, TN US 37774 Contact: DAVID SNIPES

dsnipes@recoequip.com T: (865)686-8686

F:

Diagnosis

Oil and filter change at the time of sampling has been noted. No corrective action is recommended at this time. Resample at the next service interval to monitor. The copper level is abnormal. In the absence of other significant wear metals, suspect copper due to sources other than wear (i.e. cooling core). All other component wear rates are normal. Fuel content negligible. There is no indication of any contamination in the oil. The oil viscosity is lower than normal. The BN result indicates that there is suitable alkalinity remaining in the oil. Confirm oil type.

Depot: RECLOU
Unique No: 11045586
Signed: Don Baldridge
Report Date: 28 May 2024

Submitted By: DAVID SNIPES

1469

912

867

37

89

735

Additives

ppm

ppm

ppm

ppm

ppm

ppm

Calcium

Zinc

Barium

Boron

Magnesium

Phosphorus







Graphs







