CONSTRUCTION EQUIPMENT

LIEBHERR L556 048223-1332 - Front Differential

Sample No: LH0271985

Oil Type: LIEBHERR GEAR BASIC 90 LS

Sample Information

Sample Number	LH0271985	 	
Sample Date	13 May 2024	 	
Machine Hours	1749	 	
Oil Hours	0	 	
Oil Changed	Changed	 	
Sample Status	ABNORMAL	 	

Oil Condition

Visc @ 40°C

cSt

0 195

Con	taminati	on		
Water	%	NEG	 	
Silicon	ppm	0 19	 	
Sodium	ppm	09	 	
Potassium	nnm		 	

Ä				
Wec Wec	ar Metals	5		
Iron	ppm	0 128	 	
Copper	ppm	0 104	 	
Lead	ppm	○ <1	 	
Tin	ppm	0 2	 	
Aluminum	ppm	2	 	
Chromium	ppm	1	 	
Molybdenum	ppm	07	 	
Nickel	ppm	0 2	 	
Titanium	ppm	0	 	
Silver	ppm	0	 	
Manganese	ppm	28	 	
Vanadium	ppm	0	 	

0 **Additives** Calcium ppm 0 27 Magnesium ppm 03 Zinc 071 ppm Phosphorus ppm 0 2241 Barium 0 ppm Boron ppm 08





LIEBHERR EQUIPMENT SOURCE

8200 FAYETTEVILLE ROAD RALEIGH, NC US 27603 Contact: Timothy Bailey timothy.bailey@liebherr.com T: F: (919)329-0084

Diagnosis

The oil change at the time of sampling has been noted. No corrective action is recommended at this time. Resample at the next service interval to monitor. The copper level is abnormal. All other component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:LIEBHERRNCUnique No:11047557Signed:Sean FeltonReport Date:29 May 2024Contact/Location: Timothy Bailey - LIEBHERRNC





Graphs

Ö

Ferrous Alloys

