LIEBHERR

CONSTRUCTION EQUIPMENT

LIEBHERR LH80M 1218-157090 - Rear Right Wheel Hub

Sample No: LH0282879

Oil Type: GEAR OIL SAE 80W90

5					
U Sam	ple Info	rmation			
Sample Number	_	LH0282879	LH0282890	LH0282901	
Sample Date		18 May 2024	19 Apr 2024	19 Mar 2024	
Machine Hours		1559	997	545	
Oil Hours		0	0	0	
Oil Changed		Not Changd	Changed	Not Changd	
Sample Status		ATTENTION	NORMAL	NORMAL	
<u> </u>		711.12.11.10.11			
0:16	ondition				
Visc @ 40°C	cSt	88.9	O 141	139	
Cont	aminati	on			
Water	%	NEG	NEG	NEG	
Silicon	ppm	O 6	O 10	O 10	
Sodium	ppm	03	02	0 2	
Potassium	ppm	02	0 <1	0 <1	
- * * .	ρρ	<u> </u>	0 1.	0	
(O) Was	ır Metal:	•			
			0.00		
Iron	ppm	27	36	O 34	
Copper	ppm	12	O 11	10	
Lead	ppm	0 <1	0	0	
Tin	ppm	0 0	0 <1	0 1	
Aluminum	ppm	01	0 0	0 <1	
Chromium	ppm	0 <1	0 <1	0 <1	
Molybdenum	ppm	0 4	0 0	0 <1	
Nickel	ppm	0 <1	0 0	0 <1	
Titanium	ppm	0 <1	0 0	0	
Silver	ppm	<1	0	0	
Manganese	ppm	O <1	01	O <1	
Vanadium	ppm	<1	0	<1	
Add					
Add	itives				
Calcium	ppm	181	O 118	O 139	
Magnesium	ppm	30	05	0 <1	
Zinc	ppm	① 122	O 25	O 19	
Phosphorus	ppm	O 530	O 1406	O 1382	
copilorao	PPIII	000	0 1 100	9 1002	

02

 \bigcirc 0

3



KINDER MORGAN

4301 IVERSON TRINITY, AL US 35601

Contact: RICKY JOHNSON ricky_johnson@kindermorgan.com

T:

F: (256)355-5250

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The oil viscosity is lower than normal. Confirm oil type.

Depot:KINTRIUnique No:11049372Signed:Don BaldridgeReport Date:30 May 2024

0

6

ppm

ppm

Barium

Boron

CONSTRUCTION EQUIPMENT





Graphs

