LIEBHERR





LIEBHERR L538 055489-1559 - Rear Right Wheel Hub

Sample No: LH0273554

Oil Type: LIEBHERR GEAR BASIC 90 LS

_				
J Sam	ple Info	rmation		
Sample Number		LH0273554	 	
Sample Date		08 May 2024	 	
Machine Hours		4169	 	
Oil Hours		4169	 	
Oil Changed		Changed	 	
Sample Status		ABNORMAL	 	
<u> </u>				
Oil	ondition	1		
/isc @ 40°C	cSt	189	 	
*	taminati			
Nater	%	NEG	 	
Silicon	ppm	22	 	
Sodium	ppm	0 2	 	
Potassium	ppm	2	 	
	ar Metal:			
ron	ppm	O 116	 ***	
Copper	ppm	O <1	 	
_ead r:	ppm	O <1	 	
Γin Name in the second	ppm	<1	 	
Aluminum	ppm	O 1	 	
Chromium	ppm	01	 	
Molybdenum Nickel	ppm	0 0 0 0	 	
Titanium	ppm			
i itanium Silver	ppm	<1 0	 	
Manganese	ppm	0 4	 	
Vanadium	ppm	0	 	
	itives	Ū		
Calcium	ppm	38	 	
Magnesium	ppm	4	 	
Zinc	ppm	63	 	



CHESAPEAKE BAY

2201 MINGEE DR. HAMPTON, VA US 23661

Contact: SERVICE MANAGER

T: (757)827-4778 F: (757)827-0978

Diagnosis

The oil change at the time of sampling has been noted. Resample at the next service interval to monitor.All component wear rates are normal. Moderate concentration of visible dirt/debris present in the oil. The condition of the oil is acceptable for the time in service.

Depot: CHEHAMLH
Unique No: 11075614
Signed: Don Baldridge
Report Date: 14 Jun 2024

2042

0

3

Phosphorus

Barium

Boron

ppm

ppm

ppm

CONSTRUCTION EQUIPMENT





Graphs

