CONSTRUCTION EQUIPMENT

LIEBHERR LH40M 1215-106088 - Transmission

Sample No: LH0272338

Oil Type: **DIESEL ENGINE OIL SAE 15W40**





STUFF RECYCLING 6169 LEXINGTON ROAD WINCHESTER, KY US 40391

Contact: Service Manager

T: F:

0	Oil Co	ndition			
Visc @	40°C	cSt	43.0	 	
-4					
	Conta	mination			
14/-4		0/	NEO		

Confamination							
Water	%	NEG					
Silicon	ppm	3					
Sodium	ppm	33					
Potassium	ppm	1					

Wea	Metals			
Iron	ppm	107	 	
Copper	ppm	460	 	
Lead	ppm	0	 	
Tin	ppm	0 <1	 	
Aluminum	ppm	2	 	
Chromium	ppm	O <1	 	
Molybdenum	ppm	3	 	
Nickel	ppm	0	 	
Titanium	ppm	0	 	
Silver	ppm	0	 	
Manganese	ppm	23	 	
Vanadium	ppm	0	 	

(O) Was							
Wed	ar Metal:	5					
Iron	ppm	107					
Copper	ppm	460					
Lead	ppm	0					
Tin	ppm	○ <1					
Aluminum	ppm	2					
Chromium	ppm	○ <1					
Molybdenum	ppm	3					
Nickel	ppm	0					
Titanium	ppm	0					
Silver	ppm	0					
Manganese	ppm	23					
Vanadium	ppm	0					
Additives							
Calcium	ppm	3258					
Magnesium	ppm	24					

Diagnosis

No corrective action is recommended at this time. We recommend an early resample to monitor this condition.Clutch and/or bushing/bearing wear is indicated. There is no indication of any contamination in the fluid. The condition of the fluid is acceptable for the time in service.

Depot: STUWIN Unique No: 11076877 Signed: Don Baldridge **Report Date:** 17 Jun 2024

1128

1049

0

2

ppm

ppm

ppm

ppm

Zinc

Barium

Boron

Phosphorus

CONSTRUCTION EQUIPMENT





Graphs

