LIEBHERR

CONSTRUCTION EQUIPMENT

LIEBHERR LH30M 1253-123497 - Front Right Wheel Hub

Sample No: LH0273455

Oil Type: SUPER S 80W90 LS

_ _						
Sample Information						
Sample Number	LH0273455	LH0272905	LH0212312			
Sample Date	20 Jun 2024	11 Jan 2024	30 Dec 2021			
Machine Hours	5603	4554	981			
Oil Hours	500	0	0			
Oil Changed	Changed	Changed	Changed			
Sample Status	NORMAL	NORMAL	NORMAL			

ouripio otatas		HOIIMAL	TAOT HALL	I VOI LIVI/ LL	
Oil Co	ndition				
Visc @ 40°C	cSt	125	O 120	103	
_					

Conta	mination				
Water	%	NEG	NEG	NEG	
Silicon	ppm	3	3	5	
Sodium	ppm	2	O <1	6	
Potassium	ppm	() <1	O 1	0	

10					
Wea	r Metals				
Iron	ppm	43	O 56	O 72	
Copper	ppm	5	6	1 1	
Lead	ppm	0	O	<1	
Tin	ppm	0	0	<1	
Aluminum	ppm	3	O 2	O 0	
Chromium	ppm	<1	O <1	O 1	
Molybdenum	ppm	<1	0	<1	
Nickel	ppm	○ <1	O 0	O	
Titanium	ppm	<1	0	<1	
Silver	ppm	<1	0	<1	
Manganese	ppm	<1	O	O 1	
Vanadium	ppm	0	0	0	

Additives							
Calcium	ppm	72	O 133	O 625			
Magnesium	ppm	2	O <1	3			
Zinc	ppm	25	1 9	○ 354			
Phosphorus	ppm	270	O 343	O 574			
Barium	ppm	<1	4	O 0			
Boron	ppm	2	4	7 3			



SPARTAN RECYCLING 3071 HOWARD ST SPARTANBURG, SC US 29303

Contact: SERVICE MANAGER

T: F:

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:SPASPALHUnique No:11100843Signed:Wes DavisReport Date:28 Jun 2024

CONSTRUCTION EQUIPMENT





Graphs

