

## LIEBHERR LH30M 1253-123497 - Rear Right Wheel Hub

Sample No: LH0273448

Oil Type: SUPER S 80W90 LS

## **Sample Information**

Sample Number	LH0273448	LH0272909	LH0212314	
Sample Date	20 Jun 2024	11 Jan 2024	30 Dec 2021	
Machine Hours	5603	4554	981	
Oil Hours	500	0	0	
Oil Changed	Changed	Changed	Changed	
Sample Status	NORMAL	NORMAL	NORMAL	

**Oil Condition** Visc @ 40°C cSt

	cSt	0 125	0 119	0 113
nta	mination			

Water	%	NEG	NEG	NEG	
Silicon	ppm	0 2	◯ <1	3	
Sodium	ppm	<b>○</b> <1	0	2	
Potassium	ppm	01	○ <1	0	

Ä					
Wea	r Metal	S			
Iron	ppm	0 15	8	0 10	
Copper	ppm	<b>○</b> <1	○ <1	0 2	
Lead	ppm	<b>()</b> <1	0	0	
Tin	ppm	0	0	<1	
Aluminum	ppm	3	2	0	
Chromium	ppm	<b>○</b> <1	○ <1	◯ <1	
Molybdenum	ppm	<1	0	◯ <1	
Nickel	ppm	0	0	0	
Titanium	ppm	<1	0	0	
Silver	ppm	0	0	<1	
Manganese	ppm	<1	0	◯ <1	
Vanadium	ppm	0	0	0	

٥ **Additives** Calcium ppm 33 53 274 Magnesium 14 01 ppm ○ <1 25 0 0 0 149 Zinc ppm Phosphorus 325 0 347 0 464 ppm Barium 0 03 0 ppm Boron 078 ppm 7 03





SPARTAN RECYCLING 3071 HOWARD ST SPARTANBURG, SC

SPARTANBURG, SC US 29303 Contact: SERVICE MANAGER

T: F:

## Diagnosis

Resample at the next service interval to monitor.All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:SPASPALHUnique No:11100844Signed:Wes DavisReport Date:28 Jun 2024





## Ø

Graphs

