

LIEBHERR A944 011477-744 - Front Differential

Sample No: LH

Oil Type: GEAR OIL SAE 80W90

INFORMATION SUR L'ÉCHANTILLON

0 116

Numéro d'échant.	LH	
Date d'échant.	05 Aug 2021	
Heures de la Machine	0	
Heures de l'huile	0	
Huile changée	Changed	
Statut de l'echant.	NORMAL	



ÉTAT D'HUILE

Visc 40°C

cSt

	ITAMINA	TION		
Silicium	ppm	08	 	
Sodium	ppm	01	 	
Potassium	ppm	◯ <1	 	

õ					
Métaux d'Usure					
Fer	ppm	61			
Cuivre	ppm	0 21			
Plomb	ppm	○ <1			
Étain	ppm	<mark></mark> <1			
Aluminium	ppm	0 2			
Chrome	ppm	<mark></mark> <1			
Molybdène	ppm	○ <1			
Nickel	ppm	<1			
Titane	ppm	0			
Argent	ppm	<1			
Manganèse	ppm	01			
Vanadium	ppm	<1			







LIEBHERR CANADA LTEE 4250 AUTOROUTE CHOMEDEY 13

LAVAL, QC CA H7R 6E9 Contact: Stephane Plourde Stephane.Plourde@liebherr.com T: (450)963-7174 F: (450)963-9176

Diagnostic

Resample at the next service interval to monitor. The fluid was not specified, however, a fluid match indicates that this fluid is (GENERIC) GEAR OIL SAE 80W90. Please confirm.

All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:	LIESTL
Unique No:	5278740
Signed:	Wes Davis
Report Date:	09 Sep 2021


Submitted By: Isabelle Langlois





GRAPHS

 \odot



ID du rapport: LIESTL [WCAMIS] 02443208 (Generated: 09/12/2023 11:56:10) Rev: 1