



### LIEBHERR LH40M 098208 - Transmission

Sample No: LH  
Oil Type: NOT GIVEN



**LIEBHERR CANADA LTEE**  
444 AVENUE DE LA FRICHE  
DOLBEAU-MISTASSINI, QC  
CA G8L 3M7  
Contact: Luc Trottier  
luc.trottier@liebherr.com  
T:  
F: (418)276-9844



#### INFORMATION SUR L'ÉCHANTILLON

Numéro d'échant.	LH	---	---	---
Date d'échant.	29 Jun 2023	---	---	---
Heures de la Machine	6242	---	---	---
Heures de l'huile	135	---	---	---
Huile changée	Not Chngd	---	---	---
Statut de l'échant.	NORMAL	---	---	---



#### ÉTAT D'HUILE

Visc 40°C	cSt	71.6	---	---	---
-----------	-----	------	-----	-----	-----



#### CONTAMINATION

Silicium	ppm	5	---	---	---
Sodium	ppm	13	---	---	---
Potassium	ppm	2	---	---	---



#### MÉTAUX D'USURE

Fer	ppm	17	---	---	---
Cuivre	ppm	27	---	---	---
Plomb	ppm	1	---	---	---
Étain	ppm	1	---	---	---
Aluminium	ppm	5	---	---	---
Chrome	ppm	<1	---	---	---
Molybdène	ppm	0	---	---	---
Nickel	ppm	0	---	---	---
Titane	ppm	0	---	---	---
Argent	ppm	0	---	---	---
Manganèse	ppm	11	---	---	---
Vanadium	ppm	0	---	---	---



#### ADDITIFS

Calcium	ppm	4220	---	---	---
Magnésium	ppm	22	---	---	---
Zinc	ppm	1177	---	---	---
Phosphore	ppm	1134	---	---	---
Baryum	ppm	<1	---	---	---
Bore	ppm	180	---	---	---

#### Diagnostic

Resample at the next service interval to monitor. Please specify the brand, type, and viscosity of the oil on your next sample. Please note that this is a corrected copy for data entry updates. All component wear rates are normal. There is no indication of any contamination in the fluid. The condition of the fluid is acceptable for the time in service.

Depot: LBADOL  
Unique No: 5605082  
Signed: Kevin Marson  
Report Date: 20 Jul 2023



### GRAPHS

