

LIEBHERR LH40M 098208 - Splitter Box

Sample No: LH

Oil Type: GEAR OIL SAE 80W90

INFORMATION SUR L'ÉCHANTILLON o d'échant. LH --

135

0 189

29 Jun 2023 6242

Not Changd NORMAL

Numéro d'échant.	
Date d'échant.	
Heures de la Machine	
Heures de l'huile	
Huile changée	
<u> </u>	

Statut de l'echant.

ÉTAT D'HUILE

Visc 40°C

.....

cSt

Silicium	ppm	○ <1					
Sodium	ppm	0 2					
Potassium	ppm	◯ <1					

A				
🥮 Mé	TAUX D'L	JSURE		
Fer	222	0.17		
-	ppm	0 17	 	
Cuivre	ppm	<mark></mark> <1	 	
Plomb	ppm	0 🔘	 	
Étain	ppm	0 ()	 	
Aluminium	ppm	○ <1	 	
Chrome	ppm	<mark></mark> <1	 	
Molybdène	ppm	0	 	
Nickel	ppm	0 ()	 	
Titane	ppm	0	 	
Argent	ppm	0	 	
Manganèse	ppm	○ <1	 	
Vanadium	ppm	0	 	

ø **ADDITIFS** Calcium 0 37 ppm Magnésium ppm 03 Zinc 0 22 ppm Phosphore 0 1593 ppm Baryum ppm 0 Bore ppm 01





LIEBHERR CANADA LTEE

444 AVENUE DE LA FRICHE DOLBEAU-MISTASSINI, QC CA G8L 3M7 Contact: Luc Trottier luc.trottier@liebherr.com T: F: (418)276-9844

Diagnostic

Resample at the next service interval to monitor. Please note that this is a corrected copy for data entry updates.All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.


Depot:	LBADOL
Unique No:	5605113
Signed:	Kevin Marson
Report Date:	20 Jul 2023





GRAPHS

 \odot



ID du rapport: LBADOL [WCAMIS] 02568067 (Generated: 07/20/2023 07:30:12) Rev: 2