



### LIEBHERR LH40M 098208 - Rear Right Wheel Hub

Sample No: LH

Oil Type: NOT GIVEN



**LIEBHERR CANADA LTEE**  
 444 AVENUE DE LA FRICHE  
 DOLBEAU-MISTASSINI, QC  
 CA G8L 3M7  
 Contact: Luc Trottier  
 luc.trottier@liebherr.com  
 T:  
 F: (418)276-9844



#### INFORMATION SUR L'ÉCHANTILLON

Numéro d'échant.	LH	---	---	---
Date d'échant.	29 Jun 2023	---	---	---
Heures de la Machine	6242	---	---	---
Heures de l'huile	135	---	---	---
Huile changée	Not Chngd	---	---	---
Statut de l'échant.	NORMAL	---	---	---



#### ÉTAT D'HUILE

Visc 40°C	cSt	192	---	---	---
-----------	-----	-----	-----	-----	-----



#### CONTAMINATION

Silicium	ppm	4	---	---	---
Sodium	ppm	9	---	---	---
Potassium	ppm	<1	---	---	---



#### MÉTAUX D'USURE

Fer	ppm	52	---	---	---
Cuivre	ppm	55	---	---	---
Plomb	ppm	1	---	---	---
Étain	ppm	0	---	---	---
Aluminium	ppm	<1	---	---	---
Chrome	ppm	<1	---	---	---
Molybdène	ppm	0	---	---	---
Nickel	ppm	0	---	---	---
Titane	ppm	0	---	---	---
Argent	ppm	0	---	---	---
Manganèse	ppm	1	---	---	---
Vanadium	ppm	0	---	---	---



#### ADDITIFS

Calcium	ppm	11	---	---	---
Magnésium	ppm	1	---	---	---
Zinc	ppm	40	---	---	---
Phosphore	ppm	2294	---	---	---
Baryum	ppm	<1	---	---	---
Bore	ppm	2	---	---	---

#### Diagnostic

Resample at the next service interval to monitor. Please note that this is a corrected copy for data entry updates. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot: LBADOL  
 Unique No: 5605117  
 Signed: Kevin Marson  
 Report Date: 20 Jul 2023



### GRAPHS

