



### LIEBHERR LH40M 114405-1215 - Rear Right Wheel Hub

Sample No: LH0270633

Oil Type: GEAR OIL SAE 75W90



**ELG Canada**  
4375 CORPORATE DRIVE  
BURLINGTON, ON  
CA L7L 5P7  
Contact: Service Manager

T:  
F: (905)335-9687



#### INFORMATION SUR L'ÉCHANTILLON

Numéro d'échant.	LH0270633	LH0251689	LH	LH
Date d'échant.	12 Jul 2023	31 Jan 2023	04 Jan 2022	10 May 2021
Heures de la Machine	6035	5542	4095	3004
Heures de l'huile	0	0	0	0
Huile changée	Changed	Changed	Changed	Changed
Statut de l'échant.	NORMAL	NORMAL	NORMAL	NORMAL



#### ÉTAT D'HUILE

Visc 40°C	cSt	102	93.9	100	96.1
-----------	-----	-----	------	-----	------



#### CONTAMINATION

Silicium	ppm	2	4	2	2
Sodium	ppm	<1	6	<1	<1
Potassium	ppm	<1	0	<1	<1



#### MÉTAUX D'USURE

Fer	ppm	7	50	14	11
Cuivre	ppm	15	14	46	20
Plomb	ppm	<1	<1	1	<1
Étain	ppm	0	0	0	0
Aluminium	ppm	0	<1	0	<1
Chrome	ppm	0	<1	0	<1
Molybdène	ppm	0	0	0	<1
Nickel	ppm	<1	<1	<1	<1
Titane	ppm	0	0	0	0
Argent	ppm	0	0	0	<1
Manganèse	ppm	0	1	<1	<1
Vanadium	ppm	0	0	0	0



#### ADDITIFS

Calcium	ppm	19	192	18	26
Magnésium	ppm	1	2	1	1
Zinc	ppm	24	129	31	26
Phosphore	ppm	1301	1181	1312	1183
Baryum	ppm	0	0	0	0
Bore	ppm	306	229	314	301

#### Diagnostic

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot: STR437BUR  
Unique No: 5607785  
Signed: Wes Davis  
Report Date: 18 Jul 2023



### GRAPHS

