

LIEBHERR R924 054969-1487 - Diesel Engine

Sample No: LH0246999

Oil Type:

λ.

PETRO CANADA 10W40

INFORMATION SUR L'ÉCHANTILLON

0

LH0246999

26 Jul 2023 1606

Changed

NORMAL

Numéro d'échant.	
Date d'échant.	
Heures de la Machine	
Heures de l'huile	
Huile changée	
Statut de l'echant	

D'HUILE				
cSt	0 13.2			
%	64			
	cSt	cSt 🔘 13.2	cSt 13.2	cSt 13.2

CONT	'AMINAT	ION		
% de suie	%	0 🔘	 	
Nitration (PA)	%	67	 	
Sulfatation (PA)	%	58	 	
Glycol	%	NEG	 	
Essence	%	<1.0	 	
Silicium	ppm	28	 	
Sodium	ppm	3	 	
Potassium	ppm	○ <1	 	

Ø

MéTAUX D'USURE

Fer	ppm	0 18	 	
Cuivre	ppm	02	 	
Plomb	ppm	○ <1	 	
Étain	ppm	0	 	
Aluminium	ppm	01	 	
Chrome	ppm	<mark>○</mark> <1	 	
Molybdène	ppm	5 9	 	
Nickel	ppm	0	 	
Titane	ppm	0	 	
Argent	ppm	0 ()	 	
Manganèse	ppm	○ <1	 	
Vanadium	ppm	0	 	

٥

	ITIFS			
Calcium	ppm	0 1086	 	
Magnésium	ppm	1021	 	
Zinc	ppm	0 1224	 	
Phosphore	ppm	0 1050	 	
Baryum	ppm	0 🔘	 	
Bore	ppm	0 5	 	





CLOUTHIER VENTURES LTD.

59 MATTHEWS STREET, R.R. # 5 PEMBROKE, ON CA K8A 0A6 Contact: Travis Bennett tbennett@clouthierconst.com T: (613)735-6531 F: (613)735-2769

Diagnostic

Resample at the next service interval to monitor.All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot: Unique No: Signed: Report Date: CLOPEM 5630689 Wes Davis 23 Aug 2023


Submitted By: ?

CONSTRUCTION EQUIPMENT



GRAPHS

 \odot



ID du rapport: CLOPEM [WCAMIS] 02577629 (Generated: 08/24/2023 10:24:19) Rev: 1