

LIEBHERR

CONSTRUCTION EQUIPMENT



LIEBHERR LH30M 119193-1253 - Front Left Wheel Hub

Sample No: LH0270551

Oil Type: GEAR OIL SAE 75W90



INFORMATION SUR L'ÉCHANTILLON

Numéro d'échant.	LH0270551	LH0234942	LH0230629	LH
Date d'échant.	04 Oct 2023	14 Nov 2022	06 Jun 2022	13 Jan 2022
Heures de la Machine	5149	3951	3290	2783
Heures de l'huile	0	0	0	0
Huile changée	Changed	Changed	Changed	Changed
Statut de l'échant.	NORMAL	NORMAL	NORMAL	NORMAL

BRIGHTON RECYCLING

686 COUNTY RD 64

BRIGHTON, ON

CA K0K 1H0

Contact: Angel Guan

angel@brightonrecycling.ca

T: (613)475-1001

F: (613)475-1097



ÉTAT D'HUILE

Visc 40°C	cSt	95.3	97.5	96.7	93.0
-----------	-----	------	------	------	------



CONTAMINATION

Élément	Unité	2	2	2	2
Silicium	ppm	2	2	2	2
Sodium	ppm	6	7	5	8
Potassium	ppm	0	<1	2	<1



MÉTAUX D'USURE

Élément	Unité	20	22	15	27
Fer	ppm	20	22	15	27
Cuivre	ppm	3	3	4	8
Plomb	ppm	0	0	0	0
Étain	ppm	0	0	0	0
Aluminium	ppm	<1	0	<1	<1
Chrome	ppm	0	0	0	<1
Molybdène	ppm	0	0	<1	<1
Nickel	ppm	0	<1	0	0
Titane	ppm	0	0	0	0
Argent	ppm	<1	0	0	<1
Manganèse	ppm	0	<1	<1	<1
Vanadium	ppm	0	0	0	0



ADDITIFS

Élément	Unité	86	147	118	287
Calcium	ppm	86	147	118	287
Magnésium	ppm	2	1	2	2
Zinc	ppm	21	29	52	126
Phosphore	ppm	1289	1389	1276	1269
Baryum	ppm	<1	0	0	0
Bore	ppm	299	278	294	261

Diagnostic

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot: BRI686BRI

Unique No: 5657393

Signed: Wes Davis

Report Date: 11 Oct 2023



GRAPHS

