



LIEBHERR L550 059181-1756 - Rear Left Wheel Hub

Sample No: LH0245758

Oil Type:

GEAR OIL LS 80W90

INFORMATION SUR L'ÉCHANTILLON

LH0245758 27 Sep 2023

3336

Changed NORMAL

0 183

0

Numéro d'échant.	
Date d'échant.	
Heures de la Machine	
Heures de l'huile	
Huile changée	
Statut de l'echant.	

ÉTAT D'

AT D'HUILE

Visc 40°C

.....

cSt

CONT	AMINATIO	N		
Silicium	ppm	04	 	
Sodium	ppm	03	 	
Potassium	ppm	○ <1	 	

Ô				
Mé	raux d'u	JSURE		
Fer	ppm	9 0	 	
Cuivre	ppm	0 20	 	
Plomb	ppm	○ <1	 	
Étain	ppm	<1	 	
Aluminium	ppm	○ <1	 	
Chrome	ppm	○ <1	 	
Molybdène	ppm	0 12	 	
Nickel	ppm	○ <1	 	
Titane	ppm	0	 	
Argent	ppm	<1	 	
Manganèse	ppm	08	 	
Vanadium	ppm	0	 	

ø **ADDITIFS** Calcium 461 ppm 02 Magnésium ppm Zinc 0 189 ppm Phosphore 753 ppm Baryum ppm ◯ <1 Bore 14 ppm



AV Terrace Bay Inc.

21 Mill Rd. Terrace Bay, ON CA P0T 2W0 Contact: Naqshe lqbal naqshe.iqbal@adityabirla.com T: (807)823-0761 F:

Diagnostic

Resample at the next service interval to monitor. The fluid was not specified, however, a fluid match indicates that this fluid is (GENERIC) GEAR OIL LS 80W90. Please confirm.

All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:	AV
Unique No:	565
Signed:	We
Report Date:	13 (


TTER 58055 es Davis Oct 2023





GRAPHS

 \odot



ID du rapport: AVTTER [WCAMIS] 02588989 (Generated: 10/16/2023 09:18:39) Rev: 1