

LIEBHERR

CONSTRUCTION EQUIPMENT



[(347700)] LIEBHERR L566 050281-1484 - Front Differential

Sample No: LH0274840

Oil Type: NOT GIVEN



INFORMATION SUR L'ÉCHANTILLON

Numéro d'échant.	LH0274840	LH	---	---
Date d'échant.	12 Oct 2023	07 Jul 2021	---	---
Heures de la Machine	2919	951	---	---
Heures de l'huile	0	0	---	---
Huile changée	N/A	Changed	---	---
Statut de l'échant.	NORMAL	NORMAL	---	---

MCCANN REDI-MIX INC.

R.R. #3,, 69478 BRONSON LINE

DASHWOOD, ON

CA N0M 1N0

Contact: John

john@mccannrdeimix.ca

T: (519)237-3647

F: (519)237-3644



ÉTAT D'HUILE

Visc 40°C	cSt	● 91.0	● 97.0	---	---
-----------	-----	--------	--------	-----	-----



CONTAMINATION

Silicium	ppm	● 3	● 4	---	---
Sodium	ppm	● 2	● 2	---	---
Potassium	ppm	● 0	● <1	---	---



MÉTAUX D'USURE

Fer	ppm	● 63	● 164	---	---
Cuivre	ppm	● 7	● 29	---	---
Plomb	ppm	● <1	● <1	---	---
Étain	ppm	● 0	● 2	---	---
Aluminium	ppm	● <1	● <1	---	---
Chrome	ppm	● <1	● <1	---	---
Molybdène	ppm	2	10	---	---
Nickel	ppm	● <1	● <1	---	---
Titane	ppm	0	0	---	---
Argent	ppm	<1	<1	---	---
Manganèse	ppm	2	8	---	---
Vanadium	ppm	0	0	---	---



ADDITIFS

Calcium	ppm	11	10	---	---
Magnésium	ppm	<1	2	---	---
Zinc	ppm	15	13	---	---
Phosphore	ppm	2965	3160	---	---
Baryum	ppm	<1	<1	---	---
Bore	ppm	291	281	---	---

Diagnostic

Resample at the next service interval to monitor. Please specify the brand, type, and viscosity of the oil on your next sample. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot: MCCDAS

Unique No: 5658058

Signed: Wes Davis

Report Date: 13 Oct 2023



GRAPHS

