

LIEBHERR

CONSTRUCTION EQUIPMENT



LIEBHERR L566 071885-1758 - Rear Differential

Sample No: LH0276158

Oil Type: NOT GIVEN



INFORMATION SUR L'ÉCHANTILLON

Numéro d'échant.	LH0276158	LH0265940	---	---
Date d'échant.	12 Oct 2023	11 Jun 2023	---	---
Heures de la Machine	937	500	---	---
Heures de l'huile	0	0	---	---
Huile changée	N/A	Changed	---	---
Statut de l'échant.	NORMAL	NORMAL	---	---

MONAGHAN MUSHROOMS LTD
 7345 GUELPH LINE
 CAMPBELLVILLE, ON
 CA L0P 1B0
 Contact: Steven Cargill
 s.cargill@monaghan-mushrooms.com
 T:
 F:



ÉTAT D'HUILE

Visc 40°C	cSt	● 106	● 193	---	---
-----------	-----	-------	-------	-----	-----



CONTAMINATION

Silicium	ppm	● 13	● 24	---	---
Sodium	ppm	● 6	● 10	---	---
Potassium	ppm	● <1	● 1	---	---



MÉTAUX D'USURE

Fer	ppm	● 208	● 289	---	---
Cuivre	ppm	● 117	● 259	---	---
Plomb	ppm	● 3	● 9	---	---
Étain	ppm	● 6	● 15	---	---
Aluminium	ppm	● 1	● 2	---	---
Chrome	ppm	● <1	● 2	---	---
Molybdène	ppm	0	0	---	---
Nickel	ppm	● 1	● 2	---	---
Titane	ppm	0	0	---	---
Argent	ppm	<1	0	---	---
Manganèse	ppm	2	6	---	---
Vanadium	ppm	0	0	---	---



ADDITIFS

Calcium	ppm	15	8	---	---
Magnésium	ppm	3	4	---	---
Zinc	ppm	54	50	---	---
Phosphore	ppm	3167	2413	---	---
Baryum	ppm	1	2	---	---
Bore	ppm	218	3	---	---

Diagnostic

Resample at the next service interval to monitor. Please specify the brand, type, and viscosity of the oil on your next sample. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot: MONCAM
 Unique No: 5658093
 Signed: Kevin Marson
 Report Date: 16 Oct 2023



GRAPHS

