

# LIEBHERR

## CONSTRUCTION EQUIPMENT



### LIEBHERR L580 038365-1170 - Transmission (Auto)

Sample No: LH

Oil Type: NOT GIVEN



#### INFORMATION SUR L'ÉCHANTILLON

Numéro d'échant.	LH	---	---	---
Date d'échant.	16 Oct 2023	---	---	---
Heures de la Machine	11141	---	---	---
Heures de l'huile	0	---	---	---
Huile changée	N/A	---	---	---
Statut de l'échant.	NORMAL	---	---	---

LIEBHERR CANADA LTD.

1015 SUTTON DRIVE  
BURLINGTON, ON  
CA L7L 5Z8

Contact: Steve Lehto

steve.lehto@liebherr.com

T: (905)319-9222

F: (905)319-6617



#### ÉTAT D'HUILE

Visc 40°C	cSt	● 52.9	---	---	---
-----------	-----	--------	-----	-----	-----



#### CONTAMINATION

Eau	%	NEG	---	---	---
Silicium	ppm	● 5	---	---	---
Sodium	ppm	● 2	---	---	---
Potassium	ppm	● <1	---	---	---



#### MÉTAUX D'USURE

Fer	ppm	● 10	---	---	---
Cuivre	ppm	● <1	---	---	---
Plomb	ppm	● <1	---	---	---
Étain	ppm	● 0	---	---	---
Aluminium	ppm	● 8	---	---	---
Chrome	ppm	● 0	---	---	---
Molybdène	ppm	0	---	---	---
Nickel	ppm	● <1	---	---	---
Titane	ppm	0	---	---	---
Argent	ppm	● <1	---	---	---
Manganèse	ppm	0	---	---	---
Vanadium	ppm	0	---	---	---



#### ADDITIFS

Calcium	ppm	45	---	---	---
Magnésium	ppm	1	---	---	---
Zinc	ppm	24	---	---	---
Phosphore	ppm	259	---	---	---
Baryum	ppm	<1	---	---	---
Bore	ppm	108	---	---	---

#### Diagnostic

Resample at the next service interval to monitor. Please specify the brand, type, and viscosity of the oil on your next sample. All component wear rates are normal. There is no indication of any contamination in the fluid. The condition of the fluid is acceptable for the time in service.

Depot: LIEMIS

Unique No: 5658761

Signed: Wes Davis

Report Date: 17 Oct 2023



### GRAPHS

