LIEBHERR

CONSTRUCTION EQUIPMENT

LIEBHERR R960 056281-1729 - Diesel Engine

Sample No: LH0255094
Oil Type: NOT GIVEN



ÉTATI	D'HUILE					
Visc 100°C	cSt	12.0				
Oxydation (PA)	%	211				
CONTAMINATION						

CONTAMINATION					
% de suie	%	0 0			
Nitration (PA)	%	104			
Sulfatation (PA)	%	112			
Glycol	%	NEG			
Essence	%	1			
Silicium	ppm	10			
Sodium	ppm	2			
Potassium	ppm	4			

MéT.	AUX D'US	SURE		
Fer	ppm	11	 	
Cuivre	ppm	34	 	
Plomb	ppm	4	 	
Étain	ppm	1	 	
Aluminium	ppm	3	 	
Chrome	ppm	○ <1	 	
Molybdène	ppm	47	 	
Nickel	ppm	○ <1	 	
Titane	ppm	0	 	
Argent	ppm	0 <1	 	
Manganèse	ppm	<1	 	
Vanadium	ppm	0	 	

ADDITIFS						
Calcium	ppm	1431				
Magnésium	ppm	926				
Zinc	ppm	858				
Phosphore	ppm	703				
Baryum	ppm	18				
Bore	ppm	86				





L WALTERS & SONS EXCAVATING

49-7527 STANLEY AVE. NIAGARA FALLS, ON CA L2E 6X8

Contact: Service Manager

T: (905)371-1300 F: (905)371-1599

Diagnostic

No corrective action is recommended at this time. Resample at the next service interval to monitor. The fluid was not specified, however, a fluid match indicates that this fluid is SAE 30 Diesel Engine Oil. Please confirm the oil type and grade, and specify the brand of the oil on your next sample. Metal levels are typical for a new component breaking in. Light fuel dilution occurring. No other contaminants were detected in the oil. The condition of the oil is acceptable for the time in service.

Depot: LWANIA
Unique No: 5659567
Signed: Kevin Marson
Report Date: 23 Oct 2023

LIEBHERR





GRAPHS

