

LIEBHERR

CONSTRUCTION EQUIPMENT



LIEBHERR A904 056759-005 - Front Right Wheel Hub

Sample No: LH

Oil Type: NOT GIVEN



LIEBHERR CANADA LTEE
444 AVENUE DE LA FRICHE
DOLBEAU-MISTASSINI, QC
CA G8L 3M7
Contact: Luc Trottier
luc.trottier@liebherr.com
T:
F: (418)276-9844



INFORMATION SUR L'ÉCHANTILLON

Numéro d'échant.	LH	---	---	---
Date d'échant.	18 Oct 2023	---	---	---
Heures de la Machine	14788	---	---	---
Heures de l'huile	0	---	---	---
Huile changée	N/A	---	---	---
Statut de l'échant.	NORMAL	---	---	---



ÉTAT D'HUILE

Visc 40°C	cSt	● 97.4	---	---	---
-----------	-----	--------	-----	-----	-----



CONTAMINATION

Silicium	ppm	● 2	---	---	---
Sodium	ppm	● 2	---	---	---
Potassium	ppm	● 0	---	---	---



MÉTAUX D'USURE

Fer	ppm	● 56	---	---	---
Cuivre	ppm	● 7	---	---	---
Plomb	ppm	● 4	---	---	---
Étain	ppm	● 0	---	---	---
Aluminium	ppm	● <1	---	---	---
Chrome	ppm	● 0	---	---	---
Molybdène	ppm	0	---	---	---
Nickel	ppm	● 0	---	---	---
Titane	ppm	● 0	---	---	---
Argent	ppm	<1	---	---	---
Manganèse	ppm	0	---	---	---
Vanadium	ppm	0	---	---	---



ADDITIFS

Calcium	ppm	351	---	---	---
Magnésium	ppm	2	---	---	---
Zinc	ppm	168	---	---	---
Phosphore	ppm	1307	---	---	---
Baryum	ppm	2	---	---	---
Bore	ppm	204	---	---	---

Diagnostic

Resample at the next service interval to monitor. Please specify the brand, type, and viscosity of the oil on your next sample. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot: LBADOL
Unique No: 5668901
Signed: Kevin Marson
Report Date: 25 Oct 2023



GRAPHS

